

KLEFER

Premium NA landing doors




EN 81.58:2003

KLEFER



E120

Appraise for 120 minutes integrity performance



E120 - EW60 Double Skin*

Appraise for 120 minutes integrity & 60 minutes radiation performance



E120 - Vandal Resistance

Appraise for 120 minutes integrity performance



E160

Appraise for 60 minutes integrity & insulation performance



EI120

Appraise for 120 minutes integrity & insulation performance



EW60

Appraise for 60 minutes integrity & radiation performance


AS 1530.4

KLEFER



E120

Appraise for 120 minutes integrity performance



E120 - EW60 Double Skin

Appraise for 120 minutes integrity & 60 minutes radiation performance



E120 - Vandal Resistance

Appraise for 120 minutes integrity performance



Appraise for 60 minutes integrity & insulation performance



Appraise for 120 minutes integrity & insulation performance



EW60

Appraise for 60 minutes integrity & radiation performance


GOST

KLEFER



E30

Appraise for 30 minutes integrity performance



E120 - EW60 Double Skin

Appraise for 120 minutes integrity & 60 minutes radiation performance



E120 - Vandal Resistance

Appraise for 120 minutes integrity performance



E160

Appraise for 60 minutes integrity & insulation performance



E | 120

Appraise for 120 minutes integrity & insulation performance



EW60

Appraise for 60 minutes integrity & radiation performance

GET IN TOUCH

KLEFER SA Business Park,

Kilkis, 61 100, Greece

PHONE

+30 2341075730

EMAIL

commercial@klefer.com

WEBSITE

www.klefer.com

